2 line Customer Display


The 2 line customer display we usually supply connects to the back of the Posiflex terminal. It connects via a small USB cable it is supplied with and there is a panel you can remove on the top left on the back of the Posiflex which has a USB socket it can connect to.




Once it is connected put the files from the Posiflex customer display folder in the intouch folder on the s: drive in the Winci folder on the server.

In the program go into options and the setup tab and then click more and the customer Display options should be on the right.

First Choose which port the Display is connected too. The drop down has a list of COM ports but the Posiflex USB we usually use is at the bottom of the list.



Then choose the type of Customer Display from the drop down. The list comprises different types of Customer Display but the one we usually use is the USB HID choice on the list.



The 2 line Customer Display will display the shop name and time normally. When you are in an order it will display each item you choose and its price. At the end of the order it will say "Total Amount" and display the total amount of the order.

Revision #5

Created Thu, Feb 24, 2022 5:11 PM by Simon

Updated Wed, May 17, 2023 9:58 AM by Simon